



1-Coolant inlet (G1/8")
2-Coolant outlet (G1/8")
3-Front-side pressurization (G1/8")
4-Elettric connection
  3Phases motor - Earth
  Motor thermich switch (N°1 NC)

SPEED	RPM	30000	40000
FREQUENCY	Hz	1000	1334
POWER (S1)	KW	3	3
TORQUE (S1)	Nm	0.7	0.95
TENSION	V	380	380
CURRENT	A	8.5	8





Runout taper 0.002mm

Weight: 7 Kg

PERON SPEED

SUBJECT : M-2

CUSTOMER :

Sheet:1/1

DATE : 17/04/2007