

Examples of revisions

SPINDLE HOTEL

The electrospindle is the heart of the machine, this is why it must be checked and tested regularly, even if not in use. For this purpose we offer to our customers the service of SPINDLE HOTEL: the possibility to store your spare spindles at our plant in order to keep them in optimum working conditions.

Spindle Hotel service has many advantages:

- Proper storage of spindles to guarantee their maximum functionality.
- Continuous spindle testing by our experienced technicians.
- The possibility of the shipment within 24 hours.
- The warranty period starts after delivery to the customer.

Entrusting their spindles to us, our customers can be sure of professional technical supervision, instant availability for transportation and convenient warranty conditions.





```
// Load JS file theme Galleria.loadTheme('files/galleria/themes/classic/galleria.classic.js'); // Initialize
Galleria Galleria.run('#template-gallery-c965' , { width: 'auto', height: 600, transition: 'flash',
initialTransition: 'fade', clicknext: false, showImagenav: true, showCounter: true, lightbox: true,
overlayBackground: '#0b0b0b', overlayOpacity: 0.85, imageCrop: false, imageMargin: 0, imagePan: false,
carousel: true, carouselSpeed: 200, carouselSteps: 'auto', lightboxFadeSpeed: 200,
lightboxTransitionSpeed: 300, pauseOnInteraction: true, show: 0, showInfo: true, thumbnails: true,
```

```
thumbCrop: true, thumbMargin: 5, thumbQuality: true, easing: 'galleria', transitionSpeed: 400,  
popupLinks: true, preload: 2, debug: true, queue: true, imagePosition: 'center', maxScaleRatio: 0, swipe:  
true, fullscreenDoubleTap: true, layerFollow: true, imageTimeout: 30000, fullscreenCrop: true,  
fullscreenTransition: 'fade', touchTransition: 'fade', keepSource: false, trueFullscreen: true, responsive:  
true, wait: 5000, idleMode: true, idleTime: 3000, idleSpeed: 200, thumbDisplayOrder: true,  
maxVideoSize: 'undefined', videoPoster: true, thumbPosition: 'center' });
```